



ZAVOD ZA
GRADBENIŠTVO
SLOVENIJE

SLOVENIAN
NATIONAL BUILDING
AND CIVIL ENGINEERING
INSTITUTE

Radon mitigation in Slovenia

Friderik Knez

Department for Building Physics


friderik.knez@zag.si

Dresden, 2. - 3. December 2013

Radon protection conference



Slovenia – General data

- Central European country
- 2 million inhabitants
- 3 climatic regions
 - Snow in winter
 - Medium rain
- Neighbouring
 - Croatia
 - Italy
 - Austria
 - Hungary




Slovenia and karst terrain

- Left: known caves
- Right: terrain type, regarding permeability



Measurements of radon in Slovenia

- Systematic research for some 20 years
- Shown: ground radon potential
- Detailed surveys of indoor radon in schools and kindergartens



























Buildings

- Building stock
 - Approx. 600.000 buildings, 500.000 single houses
 - Age varies
 - Building type – typical for Central Europe
- Influencing building parameters:
 - increase of tightness,
 - increase of indoor temperature

Typical building stock

- Before 1945 – CE
- 1945-1970 – brick, poor practice
- 1970-1980 gradual improvement
- Radon risk is found particularly in class 1 and 2 SHF

| Construction Year Class | Additional Classification | SFH Single Family House | TH Terraced House | MFH Multi Family House | AB Apartment Block |
|-------------------------|---------------------------|--|---|--|---|
| ... 1945 | generic (Tipična) |  SI.N.SFH.01.Gen |  SI.N.TH.01.Gen |  SI.N.MFH.01.Gen |  SI.N.AB.01.Gen |
| 1946 ... 1970 | generic (Tipična) |  SI.N.SFH.02.Gen |  SI.N.TH.02.Gen |  SI.N.MFH.02.Gen |  SI.N.AB.02.Gen |
| 1971 ... 1980 | generic (Tipična) |  SI.N.SFH.03.Gen |  SI.N.TH.03.Gen |  SI.N.MFH.03.Gen |  SI.N.AB.03.Gen |
| 1981 ... 2001 | generic (Tipična) |  SI.N.SFH.04.Gen |  SI.N.TH.04.Gen |  SI.N.MFH.04.Gen |  SI.N.AB.04.Gen |
| 2002 ... 2008 | generic (Tipična) |  SI.N.SFH.05.Gen |  SI.N.TH.05.Gen |  SI.N.MFH.05.Gen |  SI.N.AB.05.Gen |
| 2009 ... | generic (Tipična) |  SI.N.SFH.06.Gen |  SI.N.TH.06.Gen |  SI.N.MFH.06.Gen |  SI.N.AB.06.Gen |

Mitigation

- Serious mitigation for 20 years
- Sources
 - Karst terrain
 - High U content in soil
 - Fly ash
- Based on EPA guidelines
- Radon prevention – new build: (only) 3 cases


Current changes in buildings

- Energy efficiency measures cause
 - Tighter envelopes
 - Controlled ventilation / over- or underpressure
- General situation
 - Lower awareness of risks generally (radon, earthquake, flood) or
 - Denial of risk
 - Mobility and real estate prices push buildings on riskier areas (e.g. South of Ljubljana)

Cases



Radon source per case



Cases – general workflow applied

- Blueprints analyses
- Studying Rn measurements
- Interview employees and locals
- Measurements and assessment
- Design a strategy
- Apply a pilot system
- Evaluate effect
- Correct if necessary
- Finalize the system

Listening to the employees

- Different sources (older users, maintenance personell, historic sources)
 - Usually more reliable than old blueprints!
- Local information
 - Materials
 - Debreë use
 - Geological data



Knowing what you are dealing with

- Usually needed intervention
 - Opening the structure
 - Water barrier?
- Often found critical: knowledge – details on shafts
 - Unexpected difficulties (e.g. Sealed access)
- Important: detailed inspection to minimize intrusion



Details




Evaluating planned strategy

- Permeability measurements




Difficulties

- Sometimes no pressure communication is found
 - Very tight or very loose structure




Evaluation of building tightness

- Crucial in air pressurization systems
- May predict effects of energy refurbishment



Different strategies considered

- Local underpressure
 - SSD (“sub-slab depressurisation”) – often used in Slovenia
 - SMD (“sub-membrane depressurisation”) – very seldom used in Slovenia, results not so good
 - DTD (“drain – tile” depressurisation) – never used in Slovenia as is originally designed
 - Drain / shaft system – used if possible, results are good
- Overpressurization
 - Considered in latest case (not presented)









Systems execution – different variations



Critical in execution (found)

- Fan selection
- Controll absence
- Change of piping material
- Caulking material

Mitigation principle used in selected cases




Results of mitigation

| # | Building | Basic building description | Radon source | $C_{Rn,initial}$ [Bq/m ³] | $C_{Rn,inter}$ [Bq/m ³] | $C_{Rn,mit}$ [Bq/m ³] | Mitig. [year] | Mitig. principle |
|---|------------------|---|-----------------------------------|---------------------------------------|-------------------------------------|-----------------------------------|---------------|------------------------------------|
| 1 | Janče | Wooden floor, fly-ash in the structure. | Fly ash in the floor structure | Over 1.000 | less than 400 | - | 1997 | SSD |
| 2 | Lokev pri Sežani | Wooden floor, beneath large void (estimated 1,5 m ³ /m ² floor) | Soil | > 1.000 | 200-850 | - | 1997 | New floor, SSD |
| 3 | Dolenja vas | Concrete floor, long shaft network (piping, sewage) | Soil, radon distributed by shafts | 600-4.150 | 100-3.165 | < 100 - 500 | 1997 | Ventilation of shafts + SSD (part) |
| 4 | Prevole | Concrete, inaccessible walls | Soil | 3.200 | Not yet avail. | - | 2012 | SSD |
| 5 | Muljava | Concrete floor on ground, under floor suspected mixed debris | Soil | 4.000 | 380 | - | 2011 | SSD |
| 6 | Vavta vas | Concrete (?), stone walls, under floor suspected debris | soil | 1.750 | 340 | 169 | 2013 | SSD, sealing |


Janče

- Radon source is fly ash in void
- Minigation: removal of fly-ash and ventilation
- Concentration reduction
 - Before: 1020 Bq/m^3
 - After: $< 400 \text{ Bq/m}^3$




Lokev pri Sežani

- Large void in structure
- Floor reconstructed
 - Drainage system introduced
- Ventilation in chimney
- First operation successful, but fan failure due to poor fan selection
- Second operation very successful ($C_{Rn} < 200$ Bq/m³)



Case Dolenja Vas (1997)

- Initial: 600 - 4000 Bqm⁻³
- Final: 100 – 500 Bqm⁻³
- First mitigation: shaft ventilation
- Second mitigation: extension
- Third mitigation: new exhaust



Dolenja vas



Case Dolenja vas (revisited)




Dolenja vas - revisited

- Mitigation successful when commissioned
- Some modifications done afterwards (facade – air feed-in due to lack of understanding)
- New floor in library
 - Problems with sealed floor (seen very soon)
- Effect of modifications on mitigation system not known
- Change of personell dilutes instructions passed at set-up

Divača („impossible case“)

- Railway controll room
- Radon entering via large floor opening
- Opening connected to underground signalization system
 - No modification allowed due to safety reasons
 - Underground „collector“ about 5 km long – no ventilation or overpressure is possible
- Solution:
 - Instant: increased natural ventilation
 - Discussed (but not realized): mechanical ventilation with overpressure scheme


Divača




Ribnica („impossible case 2“)

- School exhibits high concentrations
- Analyzing blueprints following is found
 - The building lies on 140 cm thick concrete
 - Reason: pit beneath, leading into minor karst cave
- Exploring the possibilities it becomes clear:
 - No SSD possible due to very high volume to be ventilated
 - No overpressure possible due to central position of rooms in question
 - Sealing virtually impossible in technical rooms due to installations
- Solution:
 - Limited access and use of rooms
 - Exploring possibilities for ventilation via shafts


Ribnica



Case Muljava (2010-2011)



Case Muljava




Muljava – sum up

- Concentration
 - Before 4000 Bqm⁻³
 - After 380 Bqm⁻³
- The system in crucial points as designed
- Alterations in material selection
 - Increased drag
 - Possible issues on durability / condensation
- No monitoring has been installed to monitor pressure
 - Risk of unnoticed failure
- Results of control measurements OK


Prevole (2011-2012)



Prevole - analyses



Prevole



Prevole – sum up

- Mitigation strategy was prepared
- Due to small space problems with execution were expected
- The owner modified mitigation strategy
 - Without notice or consultation
 - Reason claimed: mainly difficult accessibility
- Real problems:
 - Lack of understanding the principles of the system
 - Unskilled technical personnel in the building
 - Distributed tasks
 - Organization of school system

Prevole - expectations

- Measurements not yet done
- Expected insufficient effect in spite of obvious effect of the ventilator
 - We have assessed that the vent is simply moving outside air
- Inspectorate is alerted about the intervention

Case Vavta vas (2012-2013)



Case Vavta vas



Vavta vas – sum up

- Concentration dropped
 - Before: 1750 Bqm⁻³
 - After: 170 Bqm⁻³
- Whole solution approach
 - Design
 - Pilot installation
 - Unofficial measurements
 - Recommendations for improvements
- The system exhibited unexpected behaviour at first
- After adjustement good results
- However: due to lack of concern
 - No official measurements ordered so far
 - No proper commissioning done

Identified risks

- **Risk 1: unauthorized interventions:** Common problem with durability of radon mitigation solution is that in most of the cases additional interventions were done.
- **Risk 2: failure to operate system properly:** radon mitigation system properly executed, however instructions for use not respected. The system was not operated continuously.
- **Risk 3: failure to comply fully with instructions for system execution:** In some cases the radon mitigation system was improperly executed due to lack of understanding of the purpose of individual components.
- **Risk 4: users rely on mitigation system without further measures:** user of the building does not feel any need for further considering concentration monitoring.

Essential measures

- Based on experience following is particularly important:
 - Radon mitigation has to be done by professionals all the way (design to execution)
 - Good commissioning and maintenance is essential
 - Clear guidelines for radon prevention are needed
 - Radon maps
 - Legislation
 - User guides
 - It seems that awareness in general public has to be high or systems will fail

Conclusions

- Radon can be successfully mitigated
- Plenty of mitigation knowledge available
- However there are „impossible“ cases as well
- Successful rate is high, however:
 - Seldom concentration is not elevated at all
 - Difficult to explain problems often occure, e.g.:
 - Rock in soil
 - Cracked and permeable walls
 - Higher concentration at 1st floor in comparison to ground floor
- Identified risks pose big threat to overall success

Thank you for your attention!